


**RE51B**

**#1 Stranded Copper Conductor
to
#5 Reinforcing Bar**

Description

#1 Stranded Copper Conductor to #5 Reinforcing Bar
Tee of Vertical Thru Reinforcing Steel & Horizontal Tap Cable

(1) #WRPSLV Wrap Sleeve required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US90	NUWTUBE90	MH1