


**RE62B**

**#2 Stranded Copper Conductor
to
#6 Reinforcing Bar**

Description

#2 Stranded Copper Conductor to #6 Reinforcing Bar
Tee of Vertical Thru Reinforcing Steel & Horizontal Tap Cable

(1) #WRPSLV Wrap Sleeve required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US65	NUWTUBE65	MH1