


**RS42SP**

**#2 Solid Copper Conductor
to
#4 Reinforcing Bar**

Description

#2 Solid Copper Conductor to #4 Reinforcing Bar
Horizontal thru Cable to Side of Vertical Reinforcing Steel

(1) #WRPSLV Wrap Sleeve required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US90	NUWTUBE90	MH1