


**RS64P**

**#4 Stranded Copper Conductor
to
#6 Reinforcing Bar**

Description

#4 Stranded Copper Conductor to #6 Reinforcing Bar
Horizontal thru Cable to Side of Vertical Reinforcing Steel

(1) #WRPSLV Wrap Sleeve required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US90	NUWTUBE90	MH1