


**RE7L4K**

**#4 Stranded Copper Conductor
to
#7 & Larger Reinforcing Bar**

Description

#4 Stranded Copper Conductor to #7 & Larger Reinforcing Bar
Tee of Vertical Thru Reinforcing Steel & Horizontal Tap Cable

(1) #CERPM3 Ceramic Packing Material required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US65	NUWTUBE65	MH1